Printed on: 4/12/2013 6:03:36 PM

National Transportation Safety Board	NTSB I	D: ANC10M	IA0	68	Aircraft Registration Number: N455A					
FACTUAL REPORT ANIATION			Occurrence Date: 08/09/2010				Most Critical Injury: Fatal			
			ence Type: A	ccic	dent	Investigated By: NTSB				
Location/Time										
Nearest City/Place	State		Zip Code		Local Time	Time Zone				
Aleknagik	AK		99555		1445	ADT				
Airport Proximity:	nce From	om Landing Facility:								
Aircraft Information Summary										
Aircraft Manufacturer			Model/Series					Type of Aircraft		
DEHAVILLAND		DHC-3				Airplane				
Revenue Sightseeing Flight: No	,	Air Medical Transport Flight: No								

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

*** Note: NTSB investigators traveled in support of this investigation and used data obtained from various sources to prepare this aircraft accident report. ***

The Safety Board's full report is available at http://www.ntsb.gov/publictn/A_Acc1.htm. The Aircraft Accident Report number is NTSB/AAR-11/03.

On August 9, 2010, about 1442 Alaska daylight time, a single-engine, turbine powered, amphibious float-equipped de Havilland DHC-3T airplane, N455A, impacted mountainous, tree-covered terrain about 10 nautical miles (nm) northeast of Aleknagik, Alaska. The airline transport pilot and four passengers received fatal injuries, and four passengers received serious injuries. The airplane sustained substantial damage, including deformation and breaching of the fuselage. The flight was operated by GCI Communication Corp. (GCI), of Anchorage, Alaska, under the provisions of 14 Code of Federal Regulations Part 91. About the time of the accident, meteorological conditions that met the criteria for marginal visual flight rules were reported at Dillingham Airport, Dillingham, Alaska, about 18 nm south of the accident site. No flight plan was filed. The flight departed about 1427 from a GCI-owned private lodge on the shore of Lake Nerka and was en route to a remote sport fishing camp about 52 nm southeast on the Nushagak River.

Updated on Jun 2 2011 4:22PM

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC10MA068

Occurrence Date: 08/09/2010

AVIATION	rence Type	e: A	Accident]								
Landing Facility/Approach Info	iormation						<u> </u>						
Airport Name	Airport ID:		Airport Elevation Ft. MSL		nway Used	Runwa	ay Lengt	th	Runw	vay Width			
Runway Surface Type:													
Runway Surface Condition:													
Approach/Arrival Flown:													
VFR Approach/Landing:													
Aircraft Information				_									
Aircraft Manufacturer DEHAVILLAND			Mode DHC		eries				Serial 206	Number			
Airworthiness Certificate(s): Normal													
Landing Gear Type: Amphibian													
	Amateur Built Acft? No Number of Seats: 11					Certified Max Gross Wt. 80					er of Engines: 1		
Engine Type: Turbo Prop				Engine Manufacturer: Model/Series: TPE 331						Rated Power: 900 HP			
- Aircraft Inspection Information													
Type of Last Inspection Da				Date of Last Inspection Time Si			ince Last Inspe	nce Last Inspection Hours				Airframe Total Time Hours	
- Emergency Locator Transmitter (E	ELT) Information												
ELT Installed?/Type Yes / C126			ELT Oper	ELT Operated? Yes ELT Aided in Locating Accident Site?									
Owner/Operator Information													
Registered Aircraft Owner	Street	Street Address 2550 DENALI ST STE 1000											
GCI COMMUNICATION CORP	>		City							State		Zip Code	
			ANCHORAGE								\Box	99503-2751	
Operator of Aircraft			Street Address 2550 DENALI ST STE 1000										
General Communication Corpo	oration (GCI)		City							Stat	- 1	Zip Code 99503-2751	
Operator Does Business As:				Operator Designator Code:									
- Type of U.S. Certificate(s) Held: N	lone												
Air Carrier Operating Certificate(s):													
Operating Certificate:					Operator Certific	cate:							
Regulation Flight Conducted Under:	: Part 91: Genera	al Aviation	on		•								
Type of Flight Operation Conducted:	: Other Work Use	e;Non-s	cheduled	J; D	omestic; Passer	nger On	nly						
		FACTU	JAL REP	OR'	T - AVIATION							Page 2	

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC10MA068

Occurrence Date: 08/09/2010

	AVIATI	Occurrence Type: Accident												
First Pilot	Information			1										
Name						State	Dat	e of Birth	Age					
On File						On F	ile			c	On File	Or	n File	62
Sex: M					Certifi	cate Num	ber:	On File	•					
Certificate(s): Airline Transport														
Airplane Rating(s): Multi-engine Land; Multi-engine Sea; Single-engine Land; Single-engine Sea														
Rotorcraft/Glider/LTA: Glider														
Instrument	Rating(s): Airpl	lane												
Instructor Rating(s): Airplane Single-engine; Instrument Airplane														
Current Bie	nnial Flight Revie	ew?												
Medical Ce	rt.: Class 1	Medica	al Cert. Status	s: With Wai	vers/Limita	ations			Date	of Last	Medical	Exan	n: 12/2009	
!														
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night Inst Actual		Instrument Simi	ment Simulated			Glider	Lighter Than Air	
Total Time														
Pilot In Cor	nmand(PIC)													
Instructor														
Instruction	Received													
Last 90 Day	ys													
Last 30 Day	ys													
Last 24 Ho	urs										<u> </u>			
Seatbelt Us	sed? Yes	Shou	ılder Harness	Used? Yes			Toxico	ology Pei	rformed? Yes Second Pilot? No					
Flight Pla	n/Itinerary													
Type of Flig	ght Plan Filed: Co	ompany VF	R											
Departure F	Point						State	. /	Airport Ide	ntifier	r Departure Time			Time Zone
Same as	Accident/Incide	ent Location							·	1430		ADT		
Destination							State	. ,	Airport Ide	rport Identifier				
Dillingham							AK		inport identifier					
Type of Cle	earance: None													
Type of Air	space:													
Weather	Information													
Source of	Wx Information:													
	Interne	et												
FACTUAL REPORT - AVIATION Page											Page 3			

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: ANC10MA068

Occurrence Date: 08/09/2010

	AVIATION	Occ	currence Type:	: Accider	nt							
Weather	Information		•					•				
WOF ID	Observation Time	Time Zone	WOF	WOF Elevation WOF Distance From Acciden				dent Site		om Accident S	Site	
DLG	1455	ADT		81 Ft. MSL				18 NM		180 Deg. Mag.		
Sky/Lowes	st Cloud Condition: Scatt				600 Ft. AG	}L	Condition of Light: Day					
Lowest Ce	illing: Overcast	10	000 Ft. AGL	Visib	oility:	3	SM	Alti	meter:	29.58	"Hg	
Temperatu	Temperature: 11 °C Dew Point:			9 °C Weat	ther Cond	litions at Acci	ident S	Site: Visual (Conc	litions		
Wind Direc	ction: 180	Wind Spo	eed: 12		Win	d Gusts: 23						
Visibility (R	RVR): Ft.	Visibility	(RVV)	SM								
Precip and/or Obscuration: Light - Mist; Light - Rain												
Accident	Information											
Aircraft Dar	mage: Substantial		Aircr	raft Fire: None	Э			Aircraft Exp	losio	n None		
							-					
- Injury Su	mmary Matrix	Fatal	Serious	Minor	None	TOTAL						
First Pil	lot	1				1]					
Second	d Pilot]					
Studen	t Pilot]					
Flight Ir	nstructor]					
Check I	Pilot						1					
Flight E	Engineer						1					
Cabin /	Attendants						1					
Other C	Crew						1					
Passen	ngers	4	4			8	1					
- TOTAL A	ABOARD -	5	4			9	1					
Other G	Ground						1					
- GRANE	O TOTAL -	5	4			9	1					

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: ANC10MA068

Occurrence Date: 08/09/2010

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

Clinton O. Johnson

Additional Persons Participating in This Accident/Incident Investigation:

Victoria Anderson Federal Aviation Administration Washington, DC

Pete B Baker Honeywell Phoenix, AZ

David Rees Viking Air Limited Sidney, BC, Canada,